




LEICHT®

Commission:

Design:

Date:

31.01.2022

View:

Plan / 1:38


Manufacturer: Leicht Collection 2021 EN

Program: 221 IKONO

Handle: 81711 Form griprail 817.284

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

31.01.2022

View:

Elevation / Scale-to-fit


Manufacturer: Leicht Collection 2021 EN

Program: 221 IKONO

Handle: 81711 Form griprail 817.284

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

31.01.2022

View:

Elevation 6 / 1:16


Manufacturer: Leicht Collection 2021 EN

Program: 221 IKONO

Handle: 81711 Form griprail 817.284

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

31.01.2022

View:

Elevation 6 / 1:16


Manufacturer: Leicht Collection 2021 EN

Program: 221 IKONO

Handle: 81711 Form griprail 817.284

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

31.01.2022

View:

Elevation / Scale-to-fit

Manufacturer: Leicht Collection 2021 EN

Program: 221 IKONO

Handle: 81711 Form griprail 817.284

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and grain patterns. Front arrangement subject to modification for manufacturer reasons.