




LEICHT®

Commission:

Design:

Date:

10.12.2021

View:

Plan / 1:38

Manufacturer: Leicht Collection 2021 EN


Program: 239 BOND I

Handle:

81404 Form griprail 814.120

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and grain patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

10.12.2021

View:

Elevation / 1:25


Manufacturer: Leicht Collection 2021 EN

Program: 239 BOND I

Handle: 81404 Form griprail 814.120

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT®

Commission:

Design:

Date:

View:

Elevation 5 / 1:17


Manufacturer: Leicht Collection 2021 EN

Program: 239 BOND1

Handle: 81404 Form griprail 814.120

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT[®]

Commission:

Design:

Date: 10.12.2021

View: Elevation 5 / 1:18


Manufacturer: Leicht Collection 2021 EN

Program: 239 BOND I

Handle: 81404 Form griprail 814.120

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics patterns. Front arrangement subject to modification for manufacturer reasons.



LEICHT[®]

Commission:

Design:

Date:

10.12.2021

View:

Elevation / Scale-to-fit

Manufacturer: Leicht Collection 2021 EN

Program: 239 BOND I

Handle: 81404 Form griprail 814.120

Worktop col.:

The images are only to provide a graphical overview; they don't fit precisely. There may be differences in the colours and graphics. Front arrangement subject to modification for manufacturer reasons.