



530  
16  
600  
3268

663  
600  
600  
600  
600  
600  
600  
19  
800  
55

250

60  
580


334


800  
67

635

250

640  
250





**LEICHT**

GERMAN  
KITCHEN  
CENTER

**Commission:**

**Design:**

**Date:** 20.03.2020

**View:** Elevation / Scale-to-fit


**Manufacturer:** Leicht Collection 2019 EN

**Program:** 421 IKONO-A

**Handle:** 88614 Recessed handle horiz. 886.

**Worktop col.:**

The images are only to provide a graphic overview; they don't fit precisely. There may be differences in the colours and gr patterns. Front arrangement subject to modification for manufacturer reasons.



**LEICHT**

GERMAN  
KITCHEN  
CENTER

**Commission:**

**Design:**

**Date:**

20.03.2020

**View:**

Elevation / 1:17


**Manufacturer** Leicht Collection 2019 EN

**Program:** 421 IKONO-A

**Handle:** 88614 Recessed handle horiz. 886.

**Worktop col.:**

The images are only to provide a graphic overview; they don't fit precisely. There may be differences in the colours and gr patterns. Front arrangement subject to modification for manufacturer reasons.



**LEICHT**<sup>®</sup>



**Commission:**

**Design:**

**Date:** 20.03.2020

**View:** Elevation / 1:18


**Manufacturer** Leicht Collection 2019 EN

**Program:** 421 IKONO-A

**Handle:** 88614 Recessed handle horiz. 886.

**Worktop col.:**

The images are only to provide a graphic overview; they don't fit precisely. There may be differences in the colours and gr patterns. Front arrangement subject to modification for manufacturer reasons.



**LEICHT**

GERMAN  
KITCHEN  
CENTER

**Commission:**

**Design:**

**Date:**

20.03.2020

**View:**

Elevation / Scale-to-fit

**Manufacturer** Leicht Collection 2019 EN

**Program:** 421 IKONO-A

**Handle:** 88614 Recessed handle horiz. 886.

**Worktop col.:**

The images are only to provide a graphic overview; they don't fit precisely. There may be differences in the colours and gr patterns. Front arrangement subject to modification for manufacturer reasons.